Energy performance certificate (EPC) recommendation report

185 UNION STREET TORQUAY TQ1 4BY Report number 4311-4853-8990-9141-5981

Valid until 5 August 2031

Energy rating and EPC

This property's current energy rating is E.

For more information on the property's energy performance, see the EPC for this property.

windows.

Recommendations

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

Changes that pay for themselves within 3 years

Recommendation	Potential impact
Consider replacing T8 lamps with retrofit T5 conversion kit.	High
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Low
In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to	Medium

Changes that pay for themselves in more than 7 years

Recommendation	Potential impact
Consider installing building mounted wind turbine(s).	Low
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Consider installing an air source heat pump.	High
Consider installing solar water heating.	Low
Consider installing PV.	Low

Property and report details

Report issued on	6 August 2021
Total useful floor area	134 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	DesignBuilder Software Ltd, DesignBuilder SBEM, v6.1.8, SBEM, v5.6.b.0
Assessor's details	

Assessor's name	Jason N Lile
Telephone	01604676005
Email	j <u>ason@bakerlile.com</u>
Employer's name	BakerLile - www.epcpartnership.com
Employer's address	BakerLile 10 The Choakles Wiootton Northampton NN4 6AP
Assessor ID	EES/019993
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Elmhurst Energy Systems Ltd